



MLS ANALYSIS

Test :
About : 0 degree and 30 degree off axis

Date: 05-02-05
Time: 11:59:21



File: 290-020o Reference: NONE



File: 290-020z